




Doc. No.: 115.TM.001		Grob Aerospace GmbH															
Chapter: 2																	
Type: G 115																	
LBA-TCDS No.: 1078		Service Bulletins (issued / in preparation)												Status: 26. Februar 2008			
SB-No.	ÄM No.	Subject	Date of issue												Remarks		
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change		Minor Change	
1078-1		Installation of additional equipment, revision of Flight manual	24.06.87	X													German language
1078-2		Installation of a spring device between aileron and rudder	05.04.88	X													
1078-2/1		Installation of a spring device between aileron and rudder	15.06.88	X													
1078-3		Special equipment for export to the Netherlands	15.06.88	X													
1078-4		Revision 3 of the Flight Manual G 115 (German Issue)	01.07.88	X													German language
1078-5		Special equipment for export to the USA	16.12.88	X													
1078-6		Approval of installation of a primer system	20.12.88	X													
1078-7		Authorized installation of the SENSENICH prop 72CK56-2-53	16.12.88	X													
1078-8		Exchange of the bowden cables...	22.05.89	X													
1078-9		Extension of operation limits, new edition of FM , inst.	24.10.89	X													
1078-10		Design standard and special equipment for export to UK	28.04.92	X	X												
1078-11		Deficiency of Prop. HOFFMANN HO 14-175 120...		X	X												not issued
1078-12		Cracks on main landing gear axles	11.06.90	X	X												
1078-12/1		Cracks on main landing gear axles	04.07.90	X	X												
1078-13		Modification of the main landing gear	07.06.91	X	X												
1078-14		Replacement of both aileron control rods no.1	05.06.90	X	X												
1078-15		Permitted modifications of the nose landing gear	06.05.91	X													
1078-16		Replacement of fuel hose on the firewall	18.09.90	X	X												
1078-17		Check of the PA bushes in the steering damper	19.11.90		X												
1078-18		Replacement of bonding lead assembly VV5	16.05.91		X												
1078-19		Permitted modifications of the nose landing gear	03.07.91	X	X												
1078-20		Installation of a rudder trim plate	23.07.91	X	X												
1078-21		Installation of maintenance free fuel lines	02.12.91	X	X												
1078-22		Installation of an Emergency Locator Transmitter	09.09.91	X	X												France only
1078-23		Installation of an additional rudder stop	16.10.91	X	X												
1078-24		Inspection of the flap hinges	23.06.92		X												
1078-25		Revision of the Flight Manuals G 115/ G 115A	13.08.92	X	X												
1078-26																	not issued
1078-27		Modification of the G115/115A to the G115B standard	16.02.93	X	X												obsolete
1078-27/2		Modification of the G115/115A to the G115B standard	21.04.93	X	X												
1078-28		Modification to the wing flap hinges	29.03.93		X												


X = applicable

Doc. No.: 115.TM.001		Grob Aerospace GmbH														
Chapter: 2																
Type:	G 115	Service Bulletins													Status: 26. Februar 2008	
LBA-TCDS No.:	1078	(issued / in preparation)														
SB-No.	ÄM No.	Subject	Date of issue	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change	Minor Change	Remarks
1078-29		Inspection of the elevator lever	22.06.93	X	X	X										
1078-29/2		Elevator lever exchange	12.08.93	X	X	X										
1078-30		Inspection or modification of elevator and elevator trim.	13.08.93	X	X	X										
1078-31		Installation of a GRP nose wheel fork	22.09.93	X	X	X										
1078-32		Installation of equipment for VFR night, CVFR,...	03.11.94				X	X	X	X						
1078-33		Modification of the nose wheel support, Installation ...	18.04.94				X		X	X						
1078-34		Reduction of the never exceed speed vne	29.04.94							X						
1078-35		Improvements and modifications during series production	06.05.94				X		X	X						
1078-36		Improvements and modifications during series production	24.05.94				X		X	X						
1078-36/2		Improvements and modifications during series production	01.06.94				X		X	X						
1078-37		Revision of the Flight Manual G 115D2	03.06.94							X						
1078-38		Stiffening of LH and RH seat shell, Installation of a..	16.06.94				X		X	X						
1078-39		Revision of the Flight Man. G 115D2 (German issue)	20.06.94							X						German language
1078-40		New issue Flight Manual G 115C (German issue)	01.05.94				X									German language
1078-41		Modification to the canopy	06.07.94				X	X	X	X						
1078-42		Revision of the Flight Manual G 115C	11.07.94				X									
1078-43		Revision of the Flight Manuals G 115C2 G 115D2	18.07.94					X		X						
1078-44		Revision of the Flight Manual G 115D	25.07.94						X							
1078-45		Modifications during series production	01.08.94				X	X	X	X						
1078-46		New issue Flight Manual G 115D (German issue)	01.06.94							X						German language
1078-47		Revision of the Flight Manuals, new issue FM	11.10.94				X	X	X	X						
1078-48		Revision of the Maintenance Manuals	17.10.94	X	X	X										
1078-49		Inspection and exchange of the carburetor temp. sens.	05.12.94	X	X	X										
1078-50		Revision FM, Installation of equipment for IFR operation	12.12.94				X	X	X	X						
1078-51		Inspection and reinforcement of the main undercarriage	18.01.95				X	X	X	X						
1078-52		Repair of the front pedal ribs, reinforced pedal levers	04.07.95				X	X	X	X						
1078-52/2		Repair of the front pedal ribs, reinforced pedal levers	31.05.96				X	X	X	X						
1078-53		Installation of alternative or optional equipment, Rev.FM					X	X	X	X						not issued
1078-54		Modifications and improvements to the G115C/D	01.09.95				X	X	X	X						
1078-55		Use of the G115C for limited acrobatic operation					X									
1078-56		Installation of a LIESE muffler to G115 with SENSENICH prop	12.12.95	X	X											


X = applicable

Doc. No.: 115.TM.001		Grob Aerospace GmbH														
Chapter: 2																
Type:	G 115	Service Bulletins												Status: 26. Februar 2008		
LBA-TCDS No.:	1078	(issued / in preparation)														
SB-No.	ÄM No.	Subject	Date of issue	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change	Minor Change	Remarks
1078-57		Replacement of the engine instruments	20.12.95				X	X	X	X						
1078-58		Modifications and improvements to the G115C/D	27.01.96				X	X	X	X						
1078-59		Reduction of the never exceed speed	10.01.96					X	X							
1078-59/2		Reduction of the never exceed speed / acro manuevres	02.09.96				X	X	X	X						
1078-59/3		Validation of the never exceed speed / acro manuevres	24.10.96				X	X	X	X						
1078-60		Replacement of the airplane identification plate	13.02.96				X									
1078-61		Reinforcement of the main undercarriage attachment	20.02.96				X	X	X	X						
1078-62		Modification of the horizontal stabilizer attachment	05.12.96				X	X	X	X						
1078-63		Optional modification of the fuel filler caps	24.11.96				X	X	X	X						
1078-64		Modification of the elevator attachment	11.12.96				X	X	X	X						
1078-64/2		Exchange of the elevator hinges	08.04.97				X	X	X	X						
1078-65		Modification of left and right rudder pedal unit	12.12.96				X	X	X	X						
1078-66		Weights and residual moments of control surfaces	10.02.97				X	X	X	X						
1078-67		Weights and residual moments of control surfaces	10.02.97				X	X	X	X						
1078-68		Modification of the flap control	29.04.97	X	X	X										
1078-69		Cancelation of the reduction of the never exceed speed	10.07.97				X	X	X	X						
1078-70		Installation of a 3-blade constant speed propeller	21.10.97						X							
1078-71		Installation of a modified air filter box	27.10.97				X	X	X	X						
1078-72		Installation of a modified muffler attachment bracket	04.02.98				X	X	X	X						
1078-73		Securing of the lower rudder bolt	12.11.97	X	X	X	X	X	X	X						
1078-74		Revision of the Flight Manual	15.09.98				X	X	X	X						
1078-75		Inspection of the trim tab hinges	15.05.98	X	X	X	X	X	X	X						
1078-76		Exchange of an oil hose	14.09.98				X	X	X	X						
1078-77		Installation of a 2-piece horizontal stabilizer	05.12.98				X	X	X	X						
1078-78		Exchange of the propeller attachment bolts	10.03.99							X						
1078-78/2		Exchange of the propeller attachment bolts	20.08.99							X						
1078-79		Revision of the Flight Manual	30.07.99								X					
1078-80		Various modifications	02.09.99								X					
1078-81		Various modifications	23.09.99								X					
1078-82		Fuel tank access panel leakage	04.10.99								X					
1078-83		Revision of the Flight Manual	13.12.99								X					


X = applicable

Doc. No.: 115.TM.001		Grob Aerospace GmbH														
Chapter: 2																
Type: G 115																
LBA-TCDS No.: 1078		Service Bulletins (issued / in preparation)												Status: 26. Februar 2008		
SB-No.	ÄM No.	Subject	Date of issue	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change	Minor Change	Remarks
1078-84		Various modifications	30.11.99								X					
1078-85		Modification of the trim control	23.11.99				X	X	X	X						
1078-86		Installation of an additional anti-icing protection	10.11.99						X	X						
1078-87		Modification to the G 115D standard	17.11.99				X	X	X	X						
1078-88		Revision of the Maintenance Manual G 115E	01.12.99								X					
1078-89		Modification of the wiring between battery and starter	21.01.00								X					
1078-90		Installation of dripping protectors	21.01.00								X					
1078-91/2		Installation of maintenance free hoses	07.02.01	X	X	X										
1078-92		Revision of the Maintenance Manual	28.03.00								X					
1078-93		Revision of the Maintenance Manual	17.05.00				X	X	X	X						
1078-94		Not issued														not issued
1078-95		Revision of the Maintenance Manual	14.06.00								X					
1078-96		Horizontal Stabilizer	13.12.01				X		X							
1078-97		Revision of the Maintenance Manual	03.08.00								X					
1078-98		Introduction of an UHF-Transmission Placard	29.08.00								X					
1078-99		Revision of the Maintenance Manual	18.12.00								X					
1078-100		Not issued														
1078-101		Installation of an additional anti-icing protection	10.11.00								X					
1078-102		Revision of the Flight Manual	27.04.01								X					
1078-102/1		Revision of the Flight Manual	16.05.02								X					
1078-102/2		Revision of the Flight Manual	16.05.02								X					
1078-102/3		Revision of the Flight Manual	16.05.02								X					
1078-102/4		Revision of the Flight Manual	10.07.02								X					
1078-102/5		Revision of the Flight Manual	14.01.04								X					
1078-103	IM115-84	Baggage compartment cover	03.10.01						X		X	X				
1078-104		Revision of the Maintenance Manual	11.01.01									X				
1078-105	OÄM1078-44	4000 hours inspection G 115C/D	22.06.04				X	X	X	X						
1078-106		Replacement of Coupling Magneto by Retarder Sys.	25.04.01								X					
1078-107	OÄM1078-23	IFR operation	08.05.02								X					
1078-108	IM115-88	Canopy jettison	27.02.02									X				
MSB1078-109	IM115EG-E30	Replacement of 2 Relays	12.09.01									X				


X = applicable

Doc. No.: 115.TM.001		Grob Aerospace GmbH														
Chapter: 2																
Type: G 115																
LBA-TCDS No.: 1078		Service Bulletins (issued / in preparation)												Status: 26. Februar 2008		
SB-No.	ÄM No.	Subject	Date of issue	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change	Minor Change	Remarks
MSB1078-110	MÄM1078-25	Modification fuel system	10.09.01								X	X				
MSB1078-110/1	MÄM1078-25	Modification fuel system	13.12.01								X	X				
OSB1078-111	IM115-87	Baggage Compartment Cover	12.09.01								X					
OSB1078-112	MÄM1078-27	Exhaust muffler installation	17.09.01								X	X				
OSB1078-112/1	IM115-90	Exhaust muffler installation	21.10.02								X	X				
OSB1078-112/2	IM115-90	Exhaust muffler installation	15.05.03				X	X	X	X	X	X				
OSB1078-113	MÄM1078-26	Alternative air filter	17.09.01								X	X				
MSB1078-114	MÄM1078-28	Avionic Rack Installation	24.09.01									X				
OSB1078-115	OÄM1078-29	Fuel tank sealant	24.09.01								X	X				
OSB1078-115/1	OÄM1078-29	Fuel tank sealant	05.02.01				X	X	X	X	X	X				
OSB1078-115/2	OÄM1078-29	Fuel tank sealant	21.03.01				X	X	X	X	X	X				
OSB1078-116	OÄM1078-32	Instrument panel clearance	12.11.01								X					
OSB1078-117	OÄM1078-29	Fuel quantity probe	14.11.01								X	X				
OSB1078-117/1	OÄM1078-29	Fuel quantity probe	21.03.02								X	X				
OSB1078-117/2	OÄM1078-29	Fuel quantity probe	31.07.02								X	X				
OSB1078-118	OÄM1078-30	Trim drive unit	20.11.01								X	X				
OSB1078-119	OÄM1078-31	Mic/ tel lead	23.11.01								X					
MSB1078-120		Brake Master Cylinder	08.01.02								X					
MSB1078-120/1		Brake Master Cylinder	04.02.02								X					
MSB1078-120/2	MÄM1078-37	Brake Master Cylinder	16.05.02								X					
MSB1078-120/3	MÄM1078-37	Brake Master Cylinder	26.09.02								X					
MSB1078-120/4	N/A	Brake Master Cylinder	12.02.07								X					
MSB1078-121		Main Gear Door Actuator	25.02.02										X			
MSB1078-122	MÄM1078-33	Hinge Bracket	25.02.02								X					
MSB1078-122/1	MÄM1078-33	Hinge Bracket	09.04.02								X					
MSB1078-122/2	MÄM1078-33	Hinge Bracket	05.12.02								X					
MSB1078-122/3	MÄM1078-33	Hinge Bracket	12.03.03								X					
MSB1078-122/4	MÄM1078-33	Hinge Bracket	30.04.03								X					
MSB1078-122/5	OÄM1078-60	Hinge Bracket	31.01.07								X					Supplements MSB 1078-122/4
MSB1078-123		Revision of Aircraft Maintenance Manuals	13.09.01	X	X	X	X	X	X	X	X	X	X			obsolete
MSB1078-123/1		Revision of Aircraft Maintenance Manuals	17.09.01	X	X	X	X	X	X	X	X	X	X			obsolete

X = applicable

Doc. No.: 115.TM.001		Grob Aerospace GmbH														
Chapter: 2																
Type: G 115																
LBA-TCDS No.: 1078		Service Bulletins (issued / in preparation)											Status: 26. Februar 2008			
SB-No.	ÄM No.	Subject	Date of issue	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change	Minor Change	Remarks
MSB1078-123/2		Revision of Aircraft Maintenance Manuals	13.05.02	X	X	X	X	X	X	X	X	X	X			obsolete
MSB1078-123/3		Revision of Aircraft Maintenance Manuals	21.01.03	X	X	X	X	X	X	X	X	X	X			obsolete
MSB1078-123/4		Revision of Aircraft Maintenance Manuals	16.01.04	X	X	X	X	X	X	X	X	X	X			obsolete
OSB1078-124	OÄM1078-36	Manifold pressure indication	12.09.02								X					
OSB1078-125																In preparation
MSB1078-126	MÄM1078-38	CO in cockpit	04.07.02	X	X	X										
MSB1078-126/1	MÄM1078-38	CO in cockpit	07.10.02	X	X	X										Supersedes MSB1078-126
OSB1078-127		Engine cooling air baffles	25.07.02								X					
OSB1078-128		Landing Gear Limits	14.06.02									X				
OSB1078-129	OÄM1078-39	Hard Landing Indicator	19.06.02									X				
MSB1078-130		Extension of Service Life		X	X	X										In preparation
OSB1078-131	OÄM1078-41	Fuel Pressure Transmitter	09.08.02								X	X				
OSB1078-132	OÄM1078-40	Oil Pressure Transmitter	06.09.02								X	X				
MSB1078-132/1	OÄM1078-40	Oil Pressure Transmitter	23.09.02								X	X				
OSB1078-133		Alternative Seat Harness	31.07.02	X	X	X	X									
MSB1078-134		Elevator Trim	15.10.02								X					
MSB1078-135	MÄM1078-39	Exchange of the Low Fuel Sensor Circuit Breaker	27.09.02								X	X				
OSB1078-136	IM115-90	Exchange of the Air Condition Service Adaptors	19.11.02										X	X		
MSB1078-137	MÄM1078-40	Fuel line fixation	10.02.03								X	X				X
OSB1078-138		Mixture lever detent									X	X				X not issued
OSB1078-139		Exhaust muffler									X	X				X not issued
OSB1078-140	OÄM1078-42	Canopy handle cover, various canopy modifications	21.03.03								X	X				X
OSB1078-140/1	OÄM1078-53	Canopy handle cover	22.09.05								X	X				X Supplements OSB1078-140
OSB1078-141	OÄM1078-43	Modification of the engine fire extinguisher	08.04.03									X				X
MSB1078-142/2		Aircraft documentation status G115, G115A	26.02.08	X	X											Supersedes MSB1078-142/1
MSB1078-143/2		Aircraft documentation status G115B	26.02.08			X										Supersedes MSB1078-143/1
MSB1078-144/4		Aircraft documentation status G115C, G115D	16.10.07				X	X	X	X						Supersedes MSB1078-144/3
MSB1078-145/9		Aircraft documentation status G115E	19.03.07								X					Supersedes MSB1078-145/8
MSB1078-146/4		Aircraft documentation status G115EG	06.12.06									X				Supersedes MSB1078-146/3
MSB1078-147/5		Aircraft documentation status G115TA	03.05.07										X			Supersedes MSB1078-147/4
OSB1078-148	IM115EG-E31	Alternative ignition switch	19.04.04								X					X

X = applicable

Doc. No.: 115.TM.001		Grob Aerospace GmbH																
Chapter: 2																		
Type: G 115																		
LBA-TCDS No.: 1078		Service Bulletins (issued / in preparation)											Status: 26. Februar 2008					
SB-No.	ÄM No.	Subject	Date of issue											Major Change	Minor Change	Remarks		
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA					
OSB1078-149		Manifold Pressure Indicator	27.05.04										X				X	
OSB1078-150		Mixture Lean Stop Device	28.09.04										X					
MSB1078-151		Hoffmann Propeller	02.07.04							X		X						
MSB1078-151/1		Hoffmann Propeller	05.07.04				X	X	X	X	X							Supersedes MSB1078-151
MSB1078-151/2		Hoffmann Propeller	14.07.04				X	X	X	X	X							Supersedes MSB1078-151/1
MSB1078-151/3		Hoffmann Propeller					X	X	X	X	X							not issued
MSB1078-152		Inspection of Fuel Hoses / Überprüfung von Benzinschläuchen	01.10.04	X	X													
MSB1078-153	MÄM1078-48	Exchange of the Main Landing Gear Swivel Bearing	22.11.04											X	X			
OSB1078-154	OÄM1078-52	Mode-S Transponder	01.12.06										X				X	
OSB1078-155		Attitude Gyro (Microtechna)											X				X	in preparation
OSB1078-156	MÄM1078-58	Slick Start Booster	06.12.06										X				X	
MSB1078-157	MÄM1078-062	Rudder Support Assy	23.01.08										X	X			X	
OSB1078-158	OÄM1078-0xx	Alternate ELT											X				X	in preparation
OSB1078-159	OÄM1078-063	Alternate brake cylinder		X	X	X	X	X	X	X	X	X	X	X	X		X	in preparation

X = applicable